

Notice of Asbestos Removal Work

To Whom It May Concern,

Clear Air Asbestos Management Ltd a licensed Asbestos Removalist (WorkSafe Class **A and B** licence: number **RB16120244** and **RA16100156** will be undertaking removal work of some Asbestos Containing Materials (ACMs) from **Mana College – Block 3**

There will be A Class removal work being conducted between the hours of **7:30AM to 6:00PM** on **15 April 2024** and is expected to be completed by **28 April 2024**. This work may need to be re-scheduled in the event of bad weather.

There will be B Class removal conducted following this, which is planned to finish 3 May 2024.

WorkSafe NZ was notified on **12 March 2024** that this licensed asbestos removal work is to be undertaken.

As we continue the excavation works, there is potential for further asbestos containing material to be found, and any further removal works will be carried out following the same processes, ensuring all H&S requirements are met. The excavation work is due to be completed by July.

Mana College management have been consulted about the nature and timing of this work, together with the safety measures to be used.

The following safety measures will be put in place and maintained for the duration of this project:

- Signs, barriers and/or temporary fencing will be installed.
- Class A removal will be conducted in an enclosed shrink-wrapped tent (smoke test to ensure integrity), and wet decontamination units set up inside the enclosure.
- Third party will issue an A class clearance certificate
- Class B removal process will then begin under Class B conditions with dry decontamination and waste storage area.
- PVA solution or water will be applied to asbestos containing materials to prevent airborne asbestos fibres dust (as required).
- Asbestos containing materials will not be broken, where possible.
- Asbestos containing material will be wrapped on site and disposed of at an approved tip site
- Air monitoring at the work site boundary will be in place for the duration of the work. If asbestos fibres above the allowable safe limit are detected, work will cease immediately and corrective measures applied
- An independent party will carry out an inspection of the site on completion of the work, and issue a clearance certificate.

The Ministry of Education website has further information about the management of asbestos and procedures to ensure the safety of all involved in or affected by the work, at the school and community. This can be found on: www.education.govt.nz/school/property-and-transport/health-and-safety-management/asbestos

Naylor Love Wellington Limited

T. 04 586 3192

E. enquiries.wn@naylorlove.co.nz

Level 1, 275 Cuba St, Te Aro, Wellington 6011
PO Box 9813, Marion Sq, Wellington 6141

naylorlove.co.nz



Additional information about asbestos removal and/or Asbestos Removal Licences can be found on WorkSafe NZ's website on www.worksafe.govt.nz/topic-and-industry/asbestos or by phoning **0800 030 040 (24 hours)**.

If you have any questions or concerns about this removal work, please feel to contact either **Jason Nicol of Clear Air Asbestos Management Ltd** on **027 775 5005** or the **Stewart Peck of Naylor Love** on **021 506 476**.

Naylor Love Wellington Limited

T. 04 586 3192

E. enquiries.wn@naylorlove.co.nz

Level 1, 275 Cuba St, Te Aro, Wellington 6011
PO Box 9813, Marion Sq, Wellington 6141

naylorlove.co.nz