



Notice of Asbestos Removal Work Wellington Girls' College

September 2021

Ceres New Zealand, LLC. A licensed Asbestos Removal Specialist (WorkSafe Class **A** Licence: number **RA16070075**) will be undertaking removal work of some Asbestos Containing Materials (ACMs) in preparation for the demolition of the Tower Block.

Starting in October and running through to late February 2022, we will be undertaking floor-by-floor asbestos removal and stripping out the building's interior and removal of exterior panels on the roof top apartment.

The majority of the asbestos removal work relates to glue under the vinyl floors, and some stable asbestos sheets to be removed from the apartment on the roof. The Tower Block work areas will be fully sealed off during this work, with industrial filtration used to ventilate the work areas. Exterior work will be confined to outside school hours, Worksafe NZ will be notified before the licensed asbestos removal work is undertaken.

All removal work will take place between the hours of 7:00AM to 5.30PM. All material is to be bagged, sealed and removed from the site outside of school hours.

Wellington Girls' College management and board have been consulted about the nature and timing of this work, together with the safety measures to be used.

The following safety measures will be put in place and maintained for the duration of this project:

- Signs and barriers will be installed.
- Asbestos-containing materials will be double bagged and removed outside school hours. Disposal to an approved tip site is confirmed by tip ticket.
- Air monitoring at the work site boundary will be placed for the duration of the work. If asbestos
 fibres above the allowable safe limit are detected, work will cease immediately, and corrective
 measures applied. The work to date indicates this is very unlikely with appropriate filtration in place
 and all boundary tests being negative.
- An independent party will carry out inspection of the site including on completion of the work, in order to issue a clearance certificate.

The Ministry of Education's website has further information about the management of asbestos and procedures to ensure the safety of all involved in or affected by the work, at the school and community. This can be found on: https://www.education.govt.nz/school/property-and-transport/health-and-safety-management/asbestos/

Additional information about asbestos removal and/or Asbestos Removal Licences can be found on WorkSafe NZ's website http://www.business.govt.nz/worksafe or by phoning 0800 030 040 (24 hours).

If you have any questions or concerns about this removal work, please feel free to contact either Asbestos Removal Specialist Business Ceres New Zealand, LLC on 021 445 715 or the Project Manager Jeremy Wilson at TBIG on 027 886 8951.